

)

)

)

)

)

)

)

)

)

Plaintiff Accu-Spec Electronic Services, Inc. ("Accu-Spec") by and through its attorneys, MacDonald Illig Jones & Britton LLP, serves these Requests for Admissions on Defendants Central Transport International, Inc. ("Central Transport") and Logistics Plus, Inc. (Logistics Plus"), pursuant to F.R.C.P. 36 requesting that the defendants serve full and complete responses to the following Requests for Admissions within 30 days of the service thereof to 100 State Street, Suite 700, Erie, Pennsylvania 16507.

1. Attached to these Requests for Admissions are invoices from Dage Industries, Inc. to Accu-Spec Electronic Services, Inc. (Documents A116-A122 and A127-A129).

ADMITTED _____ DENIED _____

2. The invoices described in Requests for Admission 1 are authentic.

ADMITTED _____ DENIED _____

3. The charges represented by these invoices were reasonable.

ADMITTED _____ DENIED _____

4. The repair work described in the invoices was reasonably required by the events alleged in the Complaint filed in the above-caption matter.

ADMITTED _____ DENIED _____

5. Accu-Spec has paid the amounts indicated on the attached invoices.

ADMITTED _____ DENIED _____

Respectfully submitted,

Thomas A. Pendleton

James E. Spoden
Thomas A. Pendleton
MacDONALD, ILLIG, JONES & BRITTON LLP
100 State Street, Suite 700
Erie, Pennsylvania 16507-1459
(814) 870-7710

Attorneys for Plaintiff
Accu-Spec Electronic Services, Inc.

CERTIFICATE OF SERVICE

I hereby certify that a copy of this document
was served upon all other parties appearing
of record by First-Class United States Mail
sent on July 26, 2004.

and
fax

Thomas A. Pendleton

835567

IN THE UNITED STATES DISTRICT COURT
FOR THE WESTERN DISTRICT OF PENNSYLVANIA

ACCU-SPEC ELECTRONIC SERVICES,
INC.,

Plaintiff)

V.)

C.A. NO.: 03-394 E

CENTRAL TRANSPORT
INTERNATIONAL, INC. and
LOGISTICS PLUS, INC.,
Defendants

Judge: McLaughlin

VERIFICATION

I, _____, am employed by defendants _____ in the position of _____ and I am authorized to execute this Verification. The Responses to the foregoing Requests for Admissions are true and correct to the best of my knowledge, information and belief.

Date: July ____, 2004



Dage Precision Industries Ltd
Rabans Lane
Aylesbury
Bucks
HP19 8RG

Tel: 01296 317800
Fax: 01296 435408

pjw@dage-group.com
www.dage-group.com


Jim Mullen
Accuspec Electronic Services
8835 Walmer Drive
Mekean,
PA, 16426

Peter Dunne Expenses From Trip To Assess Damage assessment on a DAGE-XRS-XL6500-001 - Serial No. DMXL0126 X-Ray machine supplied to Accuspec Electronic, Erie, PA.

Hello Jim,

Please find attached copies of the receipts for expenses that Peter Dunn incurred during his assessment trip to Accuspec on 14th - 16th April. If you need any clarification on any of the expenses then please let me know

Best regards


Paul Walter
Managing Director
DPI Ltd.

Expenses attached :

Flights - receipt 1 UK £993.40
Car Hire - receipt 2 - UK £112.92
Misc. subsistence - receipt 3 - US \$24.65
Hotel for two nights - receipt 4 - US \$312.58

→ U.S. \$ 1,628.48
185.11
24.65
312.58
US \$2,150.82

ALLC


PORTMAN

DAGE LIMITED
RABANS LANE
AYLESBURY
HP19 8RG
UNITED KINGDOM

PORTMAN TRAVEL LTD

105 ST PETERS STREET
ST ALBANS AL1 3HH GB
Tel:01727-862822
Fax:01727-851386

Traveller(s)
DUNN/PETERMR

INVOICE

Ordered By: ELAINE
JOB NUMBER : 1600

Branch No/Invoice No: 009/62875
Date of Invoice: 24/04/2003
Consultant/File Ref: Y07QQ/2599687
Date of Travel: 14/04/2003
Accountnumber: 1244

| Supplier | Qty | Service | Amount | Total | VAT |
|---|-----|--|--------------------|--------------------|------|
| 40004 | 2 | AVIS RENT A CAR LTD COMP 2/4DR AUTO PITTSBURGH 14 Apr 2 Days MISC CAR EXTRAS | 57.20 40.72 | 57.20 40.72 | .00% |
| EXTRAS : INSURANCE COVER / REFUELLING CHARGE / : LOCAL TAXES | | | | | |
| SUPPLIER REFERENCE : U728887666T | | | | | |
| 1000000 | 1 | BOOKING FEE | 15.00 | 15.00 | .00% |

Summary

Total cost
Total VAT

GBP 112.92
GBP 0.00

Total Due:

GBP 112.92

US \$ 185.109

VAT Registered No. 680 4034 53

*Note Standard Terms & Conditions have been updated - see overleaf

28 APR 2003

GBTA

3312

A117



504.884

DAGE LIMITED
RABANS LANE
AYLESBURY
HP19 8RG
UNITED KINGDOM

PORTMAN TRAVEL LTD

105 ST PETERS STREET
ST ALBANS AL1 3HH GB
Tel: 01727-862822
Fax: 01727-851386

Traveller(s)
DUNN/PETERMR

INVOICE

Ordered By: ELAINE
JOB NUMBER : 1600

Branch No/Invoice No: 009/62467
Date of Invoice: 11/04/2003
Consultant/File Ref: Y07QQ/2599687
Date of Travel: 14/04/2003
Accountnumber: 1244

| Supplier | Qty | Service | Amount | Total | VA |
|----------|-----|--|--------|--------|----|
| 2000 | 1 | Flight inclusive of taxes and fees 125 000009382639815 LONDON HEATHROW/BOSTON/ PITTSBURGH/BOSTON/ LONDON HEATHROW | 993.40 | 993.40 | .0 |

| | |
|-----------------|------------|
| Summary===== | |
| Total cost===== | GBP 993.40 |
| Total VAT===== | GBP .00 |
| Total Due:===== | GBP 993.40 |

US \$ 1628.48

15 APR 2003

VAT Registered No. 680 4034 53

'Note Standard Terms & Conditions have been updated - see overleaf'



A118

(2)

Scott's Apple Inc.

Applebee's
7790 Peach St
Erie, PA 16509
814-866-8210

TB#38 Michelle H

Date: 04-15-03 Time: 3:59p Guests: 1

| | |
|-----------------|------------------|
| 2 Bud Brentus | 7.00 |
| 1 Pepper Steak | 10.99 |
| 1 Apple Crisp | 3.59 |
| ***** Guest # 1 | Sub Total: 21.81 |

Check Total: 21.58
Primary : 0.23
Total Due: 21.81

Duplicate # 1
Applebee's employees
support our troops
overseas!!!

(4)

Hudson News

Logan ADE
E. Boston MA 02128

| | | |
|------------|------|----|
| Store:069 | 1.35 | D1 |
| WATER | --- | |
| Sale Total | 1.35 | |
| Cash | 1.50 | |
| Change | .15 | |

** Thank You **

TRN# 090594 04/16/03 6:29 PM
Terminal# 09, Drawer# 01, Cashier# 00830

(1)

WHSmith Gift Shop #153

| | |
|-------------------------|---------|
| 4618567 DASANI WATER 20 | 1.49 |
| SUBTOTAL | 1.49 |
| TOTAL | 1.49 |
| CASH | (10.00) |
| CHANGE | 8.51- |

3shr 21: Miranda L. 219 # 191
Register: REG1 Apr 14 2003 2:16 PM

Thank You ... How are we doing?
Customer Service 888-881-7901

Total = \$24.65

(3)

A119



GUEST CHARGES SUMMARY

Toll Free Reservations (800) 321-2211

THANK YOU FOR SELECTING COURTYARD BY MARRIOTT FOR YOUR TRIP. WE TRUST THAT YOUR EXPERIENCE WITH US HAS INCLUDED WARM AND GRACIOUS SERVICE, AND THE TYPE OF ACCOMMODATIONS EXPECTED.

WE LOOK FORWARD TO SERVING YOU AGAIN ON FUTURE TRIPS. FOR ADDITIONAL RESERVATIONS, CALL OUR TOLL-FREE RESERVATION NUMBER, (800) 321-2211.

ERIE Courtyard Staff

ERNIE CARLSON
8835 WALMER DRIVE
MCKEAN PA 16426

ROOM 406 BARD
ROOM TYPE QNQN
NO. OF GUESTS 1
RATE 89.00
CLERK JLR

ACCU SPEC ELECTRONICS

ARRIVE 14Apr03 TIME 07:31p DEPART 16Apr03 TIME 08:22a FOLIO # 6Q-97317

| DATE | REFERENCE NUMBER | DESCRIPTION | CHARGES | CREDITS |
|---------|------------------|--------------------|---------|---------|
| 14Apr03 | CT406 | CITY TAX | 4.45 | |
| 14Apr03 | LD365A | LD814-01144129(1) | 14.20 | |
| 14Apr03 | RP406 | ROOM CHARGE | 89.00 | |
| 14Apr03 | RT406 | ROOM TAX | 5.34 | |
| 14Apr03 | TE367A | LCL PH814-898-1857 | .50 | |
| 14Apr03 | TE369A | LCL PH814-323-5480 | .50 | |
| 15Apr03 | CT406 | CITY TAX | 4.45 | |
| 15Apr03 | FD717 | RESTAURANT ROOM CH | 7.00 | |
| 15Apr03 | LD462A | LD011441296317(1) | 23.00 | |
| 15Apr03 | LD463A | LD011441296317(1) | 18.60 | |
| 15Apr03 | LD467A | LD011441296317(1) | 31.80 | |
| 15Apr03 | LD519A | LD011441296317(2) | 27.40 | |
| 15Apr03 | LD559A | LD011441296317(2) | 49.40 | |
| 15Apr03 | LD624A | LD011441296317(2) | 27.40 | |
| 15Apr03 | LD669A | LD011441296317(2) | 9.80 | |
| 15Apr03 | LD806A | LD011441296317(2) | 14.20 | |
| 15Apr03 | RP406 | ROOM CHARGE | 89.00 | |
| 15Apr03 | RT406 | ROOM TAX | 5.34 | |
| 16Apr03 | FD754 | RESTAURANT ROOM CH | 7.00 | |
| 16Apr03 | LD002A | LD011441296317(2) | 14.20 | |
| 16Apr03 | LD004A | LD011441296317(2) | 9.80 | |
| 16Apr03 | LD013A | LD011441296317(2) | 67.00 | |
| 16Apr03 | LD956A | LD011441296317(2) | 14.20 | |
| 16Apr03 | LD964A | LD011441296317(2) | 9.80 | |
| 16Apr03 | LD971A | LD011441296317(2) | 9.80 | |
| 16Apr03 | LD978A | LD011441296317(2) | 9.80 | |
| 16Apr03 | LD996A | LD011441296317(2) | 14.20 | |

To enroll in Marriott Rewards, call • 1-800-249-0800

SIGNATURE _____

A120



GUEST CHARGES SUMMARY

Toll Free Reservations (800) 321-2211

THANK YOU FOR SELECTING COURTYARD BY MARRIOTT FOR YOUR TRIP. WE TRUST THAT YOUR EXPERIENCE WITH US HAS INCLUDED WARM AND GRACIOUS SERVICE, AND THE TYPE OF ACCOMMODATIONS EXPECTED.
WE LOOK FORWARD TO SERVING YOU AGAIN ON FUTURE TRIPS. FOR ADDITIONAL RESERVATIONS, CALL OUR TOLL-FREE RESERVATION NUMBER, (800) 321-2211.

ERIE Courtyard Staff

ERNIE CARLSON
8835 WALMER DRIVE
MCKEAN PA 16426

ROOM 406 BARD
ROOM TYPE QNQN
NO. OF GUESTS 1
RATE 89.00
CLERK JLR

ACCU SPEC ELECTRONICS

ARRIVE 14Apr03 TIME 07:31p DEPART 16Apr03 TIME 08:22a FOLIO # 6Q-97317

| DATE | REFERENCE NUMBER | DESCRIPTION | CHARGES | CREDITS |
|---------------|-------------------|-------------|-----------------------------|---------|
| 16Apr03 | MC08:22AM | MASTER CARD | | 577.18- |
| ***** | | | | |
| * | THIS CARD WAS | * | CARD #: MCXXXXXXXXXXXX0865 | * |
| * | ELECTRONICALLY | * | Amount: 577.18 Auth: 016156 | * |
| * | SWIPED ON 14Apr03 | * | ** Signature on File | ** |
| ***** | | | | |
| ** BALANCE ** | | | | .00 |

Total \$ 577.18
- Daye related
Calls + emails \$ 264.80
~~Total \$ 312.58~~

To enroll in Marriott Rewards, call • 1-800-249-0800

SIGNATURE _____

A121



Dage Precision Industries Ltd

Rabans Lane

Aylesbury

Bucks

HP19 8RG

Tel: 01296 317800

Fax: 01296 435408

dpi-sales@dage-group.com

www.dage-group.com

16th April 2003

Jim Mullen
Accuspec Electronic Services
8835 Walmer Drive
Mckean,
PA, 16426

Repair Estimate for Dage XRS-XL6500-001 Serial No. DMXL0126

| Reference Action | Contract \$ | Labour \$ | Materials \$ |
|--|-------------|-----------|--------------|
| 1. Repackage ready for shipment to UK | 1,092 | | |
| 2. Freight to UK (Air) | 3,262 | | |
| 3. Remove all sub - assemblies from damaged cabinet | | 1,100 | |
| 4. Dismantle Inner from outer cabinet. | | 450 | |
| 5. Removal and disposal of Lead from inner cabinet | 250 | 600 | |
| 6. Disposal of damaged inner, outer cabinets and Facia | 250 | | |
| 7. Replacement inner & outer cabinets and Front facia | | | 17,160 |
| 8. Replacement Lead | | | 2,184 |
| 9. Reassemble leaded cabinet, and refit all wiring looms | | 1,270 | |
| 10. Retest and refit Image intensifier frame assembly | | 275 | |
| 11. Retest and refit X - Y manipulator assembly | | 275 | |
| 12. Retest and refit Servo drawer assembly | | 320 | |
| 13. Retest and refit PC and associated wiring | | 280 | |
| 14. Refit X - Ray tube, Vacuum system, & Tube controller | | 420 | |
| 15. X - Ray emissions & full functional testing | | 650 | |
| 16. Miscellaneous consumables and replacement items | | | 1,000 |
| 17. Packaging ready for shipment to USA | 1,092 | | |
| 18. Freight to USA (Air) | 3,262 | | |
| Sub Totals..... | 9,208 | 5,640 | 20,344 |

Total estimated cost: \$35,192

Estimated time to repair: 3 weeks excluding freight time

N.B The costs of our Engineer Mr. Peter Dunn and associated expenses will be charged over and above the cost estimate and will be borne by Accuspec Electronics Erie PA

Signed: P.C. Dunn
Peter Dunn, Dage Precision Industries Ltd

Date: 16/4/03

A122



Dage Precision Industries Ltd

Rabans Lane

Aylesbury

Bucks

HP19 8RG

Tel: 01296 317800

Fax: 01296 435408

dpi-sales@dage-group.com

www.dage-group.com

12th August 2003

Jim Mullen
Accuspec Electronic Services
8835 Walmer Drive
McKean,
PA, 16426

Repair Charges for Dage XRS-XL6500-001 Serial No. DMXL0126

| Reference Action | Contract \$ | Labour \$ | Materials \$ |
|---|-------------|-----------|--------------|
| 1. Repackage ready for shipment to UK <i>Paid by Accuspec</i> | 0 | | |
| 2. Freight to UK (Sea) <i>Paid by Accuspec</i> | 0 | | |
| 3. Remove all sub - assemblies from damaged cabinet | | 1,100 | |
| 4. Dismantle Inner from outer cabinet. | | 450 | |
| 5. Removal and disposal of Lead from inner cabinet | 250 | 600 | |
| 6. Disposal of damaged inner, outer cabinets and facia | 250 | | |
| 7. Replacement inner & outer cabinets and Front facia | | | 17,160 |
| 8. Replacement Lead | | | 2,184 |
| 9. Reassemble leaded cabinet, and refit all wiring looms | | 1,270 | |
| 10. Retest and refit Image intensifier frame assembly | | 275 | |
| 11. Retest and refit X - Y manipulator assembly | | 275 | |
| 12. Retest and refit Servo drawer assembly | | 320 | |
| 13. Retest and refit PC and associated wiring | | 280 | |
| 14. Replace Bandit frame grabber card & test | | | 1073 |
| 15. Replace Tube control electronics rack assembly & test | | | 7663 |
| 16. Refit X - Ray tube, Vacuum system, & Tube controller | | 420 | |
| 17. X - Ray emissions & full functional testing | | 650 | |
| 18. Miscellaneous consumables and replacement items | | | 1,000 |
| 19. Packaging ready for shipment to USA | 1,092 | | |
| 20. Freight to USA (Air) <i>Paid by Accuspec</i> | | | |
| Sub Totals..... | 1,592 | 5,640 | 29,080 |

Total repair costs: \$36,312

N.B The costs of our Engineer Mr. Peter Dunn and associated expenses will be charged over and above the cost estimate and will be borne by Accuspec Electronics Erie PA

PO# 86304

A127



Dage Precision Industries Ltd
Rabans Lane
Aylesbury
Bucks
HP19 8RG

Tel: 01296 317800

Fax: 01296 435408

dpi-sales@dage-group.com
www.dage-group.com

Jim Mullen
Accuspec Electronic Services
8835 Walmer Drive
Mckean,
PA, 16426

Damage assessment on a DAGE-XRS-XL6500-001 - Serial No. DMXL0126 X-Ray machine supplied to Accuspec Electronic, Erie, PA.

The outside of the cabinet was inspected and a straight edge used to gauge the extent of the damage. Distortion to varying degrees has occurred along the full length of the front fascia shelf. In particular the front lower right hand corner which has been pushed back into the outer cabinet. The amount of deformation to the outer cabinet would indicate that damage has also occurred to the lead on the inner cabinet, this would compromise the effectiveness of the x-ray shielding and make the machine dangerous to use. The front fascia is severely bent and buckled making it beyond economical repair.

The inside of the inner cabinet was inspected using a flash light with particular attention given to the welded seams, though there is a small amount of flaking paint there are no obvious signs of physical damage to the inside of the cabinet. There are also no visual signs of damage to any of the major sub-assemblies within the cabinet. The transit brackets were checked for signs of stress, none could be seen.

The rear doors are correctly aligned and the hinges show no evidence of movement. The rear door securing bolt alignment is correct. The doors were easily opened and closed securely.

The front loading door has clearance all-round and has not come into contact with the front fascia, clearance at the bottom of the door was less than that at the top.

The Gulmay power supply has not moved and shows no sign of damage.

The servo drawer, PC, vacuum pump and associated parts in the electronics tunnel appeared to be in good order.

All boxed accessories were inspected at the customer premises. The aluminium cover was removed from intensifier head and there was no damage evident. All the other accessories were found to be in order.

Damage appears to be restricted to the front fascia, outer cabinet and the lead only. There may be however damage to electronic components that will not be seen until the machine is powered up and tested.

The packaging displayed extensive damage to the front and base. Some of the machine castors had penetrated through the pallet and the machine was resting on bottom edge of the outer cabinet.

The best course of action would be to return the machine complete to the UK for repair and test.

Report compiled by P. C. Dunn Engineer for Dage Precision Industries Ltd. 15 April 2003

A handwritten signature in black ink, appearing to read "P. C. Dunn".
Signed: Peter Dunn

16 / 4 / 03
Date

A128



Dage Precision Industries Ltd
Rabans Lane
Aylesbury
Bucks
HP19 8RG

Tel: 01296 317800

Fax: 01296 435408

dpi-sales@dage-group.com
www.dage-group.com

Jim Mullen
Accuspec Electronic Services
8835 Walmer Drive
Mckean,
PA, 16426

Damage assessment on a DAGE-XRS-XL6500-001 - Serial No. DMXL0126 X-Ray machine supplied to Accuspec Electronic, Erie, PA.

The outside of the cabinet was inspected and a straight edge used to gauge the extent of the damage. Distortion to varying degrees has occurred along the full length of the front fascia shelf. In particular the front lower right hand corner which has been pushed back into the outer cabinet. The amount of deformation to the outer cabinet would indicate that damage has also occurred to the lead on the inner cabinet, this would compromise the effectiveness of the x-ray shielding and make the machine dangerous to use. The front fascia is severely bent and buckled making it beyond economical repair.

The inside of the inner cabinet was inspected using a flash light with particular attention given to the welded seams, though there is a small amount of flaking paint there are no obvious signs of physical damage to the inside of the cabinet. There are also no visual signs of damage to any of the major sub-assemblies within the cabinet. The transit brackets were checked for signs of stress, none could be seen.

The rear doors are correctly aligned and the hinges show no evidence of movement. The rear door securing bolt alignment is correct. The doors were easily opened and closed securely.

The front loading door has clearance all-round and has not come into contact with the front fascia, clearance at the bottom of the door was less than that at the top.

The Gulmay power supply has not moved and shows no sign of damage.

The servo drawer, PC, vacuum pump and associated parts in the electronics tunnel appeared to be in good order.

All boxed accessories were inspected at the customer premises. The aluminium cover was removed from intensifier head and there was no damage evident. All the other accessories were found to be in order.

Damage appears to be restricted to the front fascia, outer cabinet and the lead only. There may be however damage to electronic components that will not be seen until the machine is powered up and tested.

The packaging displayed extensive damage to the front and base. Some of the machine castors had penetrated through the pallet and the machine was resting on bottom edge of the outer cabinet.

The best course of action would be to return the machine complete to the UK for repair and test.

Report compiled by P. C. Dunn Engineer for Dage Precision Industries Ltd. 15 April 2003

.....
Signed: Peter Dunn

.....
Date

A129